



BULLETIN NO. 112105

DATE: November 21, 2005

TO: All Pennco Boiler Customers

FROM: Technical Service Department

TITLE: Burner Tube Change

MODELS AFFECTED

15B Series	Nat and LP gas	Spark and Std. pilot
-------------------	----------------	----------------------

SITUATION

The current burner tubes used on the 15B Series Pennco Boilers have been obsoleted and replaced with a new style burner of advanced design (see photo 1). The new burners were designed for quiet operation and better performance under harsh field conditions, i.e. L.P. Gas.

Model 15B-295

The 15B-295 requires a slight change to the burner door to accommodate the new tubes. Kit no. **550001348** is to be used in the event the new tubes are used to replace old style tubes in the field. This kit includes a new burner door along with the new burner tubes (see photo 2).

Models 15B-045 thru 15B-245

The new style tubes, part no. **240005543** is a direct replacement for the old style tubes on the 15B-045 thru 15B-245 and require no burner door change.

EFFECTIVE DATE:

As of November 14, 2005, all 15B Series boilers began being built with the new style burner tubes.

OVER




Photo 1




Photo 2

If you should have any questions, please feel free to contact our **Technical Service Department** at **1-800-325-5479**.